• ATELIER produced & distributed by Fortuny S.r.l. San Marco, 2425 . 30124 Venezia - Italy p+39 041 5236953 . info@fortuny.it www.fortuny.it CESENDELLO / art. G 019 AP / glass assembly instructions / wall 1 x MAX 5W E12 110-120V 50-60 Hz ATTENTION: do not use abrasive products to clean this lamp but only a damp cloth. **WARNING**: the safety is guaranteed only with appropriate use of these instructions, Our creations may show slight imperfections due to the special handwork required on each piece. Variations are one of the features which make each of our products an original and unique item. which must be kept for future reference. We recommend the installation by qualified personnel.

VENEZIA •

## **GENERAL:**


- Read all instructions and review diagrams beginning with the installation of the fixture.
- All electrical connections must be in accordance with local codes, ordinances or national codes. If you are unfamiliar with methods of electrical wiring, secure the services of a qualified licensed electrician.

## **BEFORE BEGINNING INSTALLATION:**

- Turn off the electricity to the outlet box at the circuit breaker or fuse box.
- If you are replacing an existing fixture, remove the old fixture and expose the supply wiring.
- Remove the old cross bar.


## **ELECTRICAL CONNECTIONS:**

- While supporting the fixture, connect the white wire from the fixture to the white or marked wire of the supply circuit.
- Connect the black fixture to the black supply wire.
  Connect the ground wire bare copper wire to the ground conductor of the supply circuit. Secure with UL listed wire connectors suitable for the size, type and number of wires. Make sure that there are no loose strands of wire and that there are no loose connections.
- Spread the electrical wire connections apart and back into the outlet box.




## **INSTALLING FIXTURE:**


- 1. Before starting the installation, disconnect the power.
- 2. Fix element **A** to the outlet box using the outlet box screws.
- 3. Make the electrical connections. Refer to the section titled Electrical connections.




4. Place the metal plate **B** over the element **A**. Then screw the screw **C** and install bulb. Do not exceed the maximum wattage for this fixture. Refer to the wattage warning label attached to the fixture for maximum allowable wattage.



**ATTENTION**: place the lampshade in the correct position. Holes **D** must be in the correct front position.



 Please unscrew the metal sphere E by hand and delicately insert lampshade until is firmly secured to the frame.
 Then secure the lamp screwing the screw E.



6. Restore the electricity and test.